

Risk Assessment For Operation of Line Marking

Assessor: R.Pinion **Reviewed by:**

Date: 03/2013

Statutory Requirements:

- All operators must be trained in safe operations and read this assessment prior to use.
- All tools and materials must be used and stored safely

PPE Requirements:

- Steel toecap boots
- Non-snag clothing
- Gloves

COSHH: See assessments for Chalk marking paint and turf paint.

Waterbeach Parish Council-Risk Assessment

Hazard	Risk	Likelihood	Controls	Likelihood if Controls applied
Paint/Chalk	Dust may cause irritation of eyes and airways	Medium	Wear gloves to handle materials, wear goggles if appropriate.	Low
Marking Machine	Sharp edges	Low	Wear gloves to clean the machine and during the operation.	Low

Safe System of Work

<u>Do</u>	<u>Do Not</u>
Ensure you work safely and sensibly	Use a defective tool
Ensure you check the work area for debris that could cause slips or trips	Leave tools and materials on the floor or where they could be a hazard
Ensure you put the machine and materials away safely after work	
Follow COSHH assessments as required	
Wear Appropriate PPE as detailed above	